


**RH  PETERSON co.**  
**Technical Services Bulletin 17-01**

**Aurora and AOG “L” Model Power Reset Guidelines**

If the power supply to an Aurora or AOG “L” model grill is interrupted - and you have already checked the GFCI and circuit breaker – in most cases simply unplugging the power cord from the line power and waiting ten minutes before reconnecting will reset the thermal fuse inside the power supply. The label below can be found on the power cord and provides this guidance.



If the power supply has to be continually reset, or if additional help is needed, please contact the R.H. Peterson Technical Services Department at 800 332-3973.